0009

1594 West North Temple, Suite 1210

Salt Lake City, Utah 84114-5801

OK

Michael O. Leavitt Governor

Robert L. Morgan Executive Director Lowell P. Braxton Division Director

(801) 538-5340 telephone (801) 359-3940 fax (801) 538-7223 TTY (801) 538-7223 TTY www.nr.utah.gov

PO Box 145801

August 8, 2002

TO:	Internal File				
THRU:	Daron Haddock, Permit Supervisor	-			
FROM:	David Darby, Senior Reclamation Specialist				
RE:	1999, Forth Quarter Water Monitoring, Consolidated Valley Mine, C/015/007-WQ99-4	ution Coal Co	mpany, Hidden		
	submitted for all of the MRP required sites?  y sites not monitored and reason why, if known:	YES [X]	NO[]		
2. On what date does the MRP require a five-year resampling of baseline water data. See Technical Directive 004 for baseline resampling requirements. Consider the five-year baseline resubmittal when responding to question one above. Indicate if the MRP does not have such a requirement.					
Resampling d	ue date	•			
Does not state	a date				
	equired parameters reported for each site? ents, including identity of monitoring site:	YES [X]	NO[]		
•	gularities found in the data?  ents, including identity of monitoring site:	YES[]	NO [ X ]		
5. Were DM	R forms submitted for all required sites?	1 <sup>st</sup> month, 2 <sup>nd</sup> month,	YES[] NO[ YES[] NO[		
Ident	ify sites and months not monitored:	3 <sup>rd</sup> month,			

DMR forms are not required, because there are no UPDES discharge points. **Utah!** 

Page 2 C/015/007-WQ\_99-4 August 8, 2002

6. Were all required DMR parameters reported?  Comments, including identity of monitoring site:	YES[]	NO[]		
N/A				
7. Were irregularities found in the DMR data?  Comments, including identity of monitoring site:	YES[]	NO[]		
N/A				
8. Based on your review, what further actions, if any, do you recommend?				
None				
P:\GROUPS\COAL\WP\015007.HID\WATER QUALITY\WQ_99-4.DOC				